

Under Review Notification

Raised By: S Drouin

Product #: D120-639-021

Date: 18.04.19

Product Name: WEARPLATE

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPF Under Review	Product Specifications Under Review ("Bluefiles")		
D120-639-021	DSI 9623 Rev A	Y	Y	N	Y	N	N	Y	712	Design Change
D4677-1	D4677 Rev A	Y	Y	N	Y	N	N	N	712	Revise Drawing

Description of Issue:

D120-639-021 Interference between the Saddle and D4677-1 Wearplate
Can't send D120-639-021 to Customers because of fit issues with D4677-1.

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider